

**ARM[®] Cortex[®]-M0
32-bit Microcontroller****NuMicro[®] Family
NUC230/NUC240 Series BSP
Revision History**

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design. Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com

Revision 3.01.001 (Released 2015-08-18)

1. Fixed the clock selection bug in SCUART_TxRx() sample code.
2. Fixed the reset handler from __iar_program_start to Reset_Handler.
3. Fixed the bug of clearing wrong enable bit in UART_SelectLINMode() of UART driver.
4. Fixed CAN_STATUS_LEC_Msk from 0x03 to 0x07.
5. Fixed SC_UACTL_UA_MODE_EN_Msk define error from (3ul << SC_UACTL_UA_MODE_EN_Pos) to (1ul << SC_UACTL_UA_MODE_EN_Pos).
6. Fixed the wrong SC1 and SC2 clock source select shift position in MODULE constant definitions.
7. Fixed the wrong definition bug of PS2_DISABLE_OVERRIDE() and PS2_ENABLE_OVERRIDE().
8. Fixed the bug of PS2_Write() in PS2 driver.
9. Removed ReadDID() function from FMC driver as It is no longer supported.
10. Updated USB driver to improve reliability and compatibility.
11. Added NuEdu sample code.
12. Added INT 'MCUIRQ' and 'MCUIRQCR' bit field definitions.
13. Added CLK_EnableSysTick() and CLK_DisableSysTick() to control SysTick and select SysTick clock source.
14. Added SPI_FIFO_SIZE constant definition.
15. Added USB device sample code.
16. Improved USB driver for adding more USB sample code.

Revision 3.00.002 (Released 2015-05-11)

1. Fixed the wrong baud rate returned by SCUART_SetLineConfig() in SCUART driver.
2. Fixed SCUART_Open() of SCUART driver for wrong clock calculation and return value.
3. Fixed SC_SET_STOP_BIT_LEN define error.
4. Fixed the bug of ADC_IS_DATA_OVERRUN() that the input parameter is channel number but channel bit mask.
5. Updated CAN clock setting in CAN_Open() of CAN driver to comply with different system clocks.
6. Fixed the wrong return value bug of CLK_SetCoreClock() in CLK driver.
7. Fixed CLK_SetModuleClock() error for PWM clock selection in CLK driver.
8. Fixed the bug of CLK_SysTickDelay() that COUNTFLAG may not be cleared in CLK driver.
9. Fixed the GPIO_ENABLE_DOUT_MASK() and GPIO_DISABLE_DOUT_MASK() implement inverse error in GPIO driver.
10. Fixed the close wrong I²C bug of I2C_Close() in I²C driver.
11. Fixed API declare name from I2C_SetClockBusFreq() to I2C_SetBusClockFreq() in I²C driver.
12. Fixed the clear RS-485 address byte detection flag bug to clear one flag at one time in RS485_HANDLE() of UART driver.
13. Added one more zero packet when BULK IN transfer is end by max packet size packet at last packet in VCOM sample code.
14. Fixed UA_LIN_CTL[4] bit field name as 'MUTE_EN' not 'WAKE_EN' in UART LIN_CTL bit field definitions of header file.
15. Fixed the wrong mask definition of SC_TRSR_TX_POINT_F_Msk and SC_TRSR_RX_POINT_F_Msk in header file.
16. Fixed the wrong bit definition of WAKEUP_EN in USB_INTEN register of header file.

17. Fixed the channel 0 trigger disabled bug when channel 1~3 trigger enabled in PWM_EnableADCTrigger() of PWM driver.
18. Fixed the bug that channel 0 trigger will be disabled when channel 1~3 trigger are enabled in PWM_EnableADCTrigger() of PWM driver.
19. Fixed SCUART_PARITY_NONE/SCUART_PARITY_EVEN/SCUART_PARITY_ODD definition bug in SCUART driver.
20. Fixed four macro definitions of SPI driver to avoid affecting non-target SPI_SS pin including SPI_SET_SS0_HIGH() SPI_SET_SS1_HIGH() SPI_SET_SS0_LOW() SPI_SET_SS1_LOW().
21. Fixed the clear flag bug to clear one flag at one time in UART_ClearIntFlag(). It should be '(uart)->FSR = UART_FSR_RS485_ADD_DETF_Msk' but '(uart)->FSR |= UART_FSR_RS485_ADD_DETF_Msk'.
22. Fixed the clear wrong flag bug in UART_RS485_CLEAR_ADDR_FLAG().
23. Fixed UA_LIN_CTL[4] bit field name as 'MUTE_EN' not 'WAKE_EN' in UA_LIN_CTL constants definitions in UART driver.
24. Added SPI_SET_SS_LEVEL() macro definition in SPI driver to allow user to set both SPI_SS pins.
25. Added a lack macro SYS_IS_LVR_RST() to SYS driver.

Revision 3.00.001 (Released 2014-05-05)

1. Supported NUC230/NUC240
2. Supported latest NuMicro Family Driver API.
3. Supported register based and driver based sample code.
4. Added USB CCID Card Reader sample code

Revision 1.01.001 (Released 2013-07-25)

1. Supported NUC230_240 BN version.
2. Split driver samples into small one for easy reference.
3. Added readme file in root directory for quick reference for BSP directory and sample code.

Revision 1.00.002 (Released 2012-11-09)

1. Fixed CAN, Smart Card, and GPIO driver bugs.
2. Modified the unlock function to do retry when fail to unlock.

Revision 1.00.001 (Released 2012-08-04)

1. Initial Release.

Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

*Please note that all data and specifications are subject to change without notice.
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*