

ARM® Cortex®-M0
32-bit Microcontroller

NuMicro® Family
M071R/M071S Series BSP
Revision History

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design. Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com

Revision 3.00.004 (Released 2026-08-25)

1. Add software disconnect and reconnect API in USB_D.
2. Update ISP_SPI sample to add interrupt mask protection for ParseCmd().
3. Add a macro to wait for the I2C bus status to be cleared.
4. Add the macro to the sample code to avoid re-entering the interrupt before the register write is complete, which could lead to an incorrect I2C_STATUS0 value of 0xf8.
5. Add read/write byte related functions to the I2C driver.
6. Disable I2C_IRQ until ParseCmd() is completed to prevent ISP from triggering an interrupt and fetching data prematurely.
7. Support VSCode multi-toolchain projects.
8. Add USB_D_HID_Mouse2 sample code.
9. Add Schmitt trigger configuration for I2C pins.
10. Add description: GC mode is not supported for device address calling.
11. Revised ISP_I2C Schmitt trigger configuration.

Revision 3.00.003 (Released 2024-11-11)

1. Update USB_D HID keyboard sample code to support LED status.
2. Modify to pass USB-IF CV - Chapter 9 & Class test.
3. Fix USB_D_MassStorage_CDROM crash on Linux.
4. Modify HID polling interval - bInterval to 10.
5. Add SPI_TRIGGER_TX_RX_PDMA and SPI_DISABLE_TX_RX_PDMA API in SPI driver.
6. Enable LVR in SYS_PowerDown_MinCurrent sample code to prevent power on/off fail.
7. Modify UART_RS485_Master/Slave sample code.
8. Add timeout handler for infinite loop.
9. Fix infinite loop.

Revision 3.00.002 (Released 2023-05-19)

1. Modify VendorName of Nu_DFU.inf.
2. Set FlashSelect of ISP_DFU sample code to LDROM.
3. Fix SPI_Loopback_GCC sample code issue.
4. Fix I2C_EEPROM and I2C_GCMode failed in GCC.
5. Modify startup_M071M.s in IAR/ARM file.
6. Modify sample code for keil compiler 6.
7. Add SYS_PowerDown_MinCurrent sample code.
8. Update SPI_Loopback sample code.

Revision 3.00.001 (Released 2020-07-10)

1. Initial Release.

Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

*Please note that all data and specifications are subject to change without notice.
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*